
## ENLARGE

## **ATLAS**

For warranty information, latest products, and news visit us at:  $nsnovelties. \\ com$ 

## ΡΙ ΔΥ

- Press & hold top power button for 3 seconds until the indicator light turns on to power on and enter standby mode.
- 2. Quick press middle suction button to cycle through 3 suction speeds.
- 3. Press & hold bottom release button to release suction.
- 4. Press & hold top power button to turn device off.



## CARE

- \* Turn off device when not in use.
- \* Wash after each use with liquid anti-bacterial soap
- \* Pat dry with a cotton towel and allow to air dry completely.

**Product Dimensions:** 11.65 x 2.8 x 2.8 (in)

IPX Rating: IPX6
Battery: AAA
Modes: 3

