# Renegade

## SLINGSHOT II CR AND PROSTATE STIMULATOR

For warranty information, latest products, and news visit us at:  $\begin{tabular}{l} \textbf{nsnovelties}. com \end{tabular}$ 

#### CADE

- ★ Turn off device when not in use.
- $\ensuremath{\bigstar}$  Do not operate the device while charging.
- $\ensuremath{\mbox{\$}}$  Please follow the charge times indicated in the device specifications.
- $\boldsymbol{\texttt{\#}}$  Wash after each use with liquid anti-bacterial soap and water.
- \* Pat dry with a cotton towel and allow to air dry completely.

**Product Dimensions:** 4.72 x 1.3 x 4.02 (in)

Remote: 2.64 x 1.34 x 0.87 (in)

IPX Rating: Plug: IPX6, Remote: IPX7

Battery: Stimulator: Lithium Ion,

Remote: AAA

Charge Time: Do not exceed 120 minutes

Run Time: 70 minutes

Modes: 30




#### PLA

- Press & hold power button on device for 2 seconds to enter standby mode.
- Quick press power button to activate and to cycle through modes.
- Press & hold power button on device for 2 seconds to power on/off.

### PLAYING WITH REMOTE

- \* To use the remote the device must be powered on.
- Press & hold power button on remote for 2 seconds to power on/off.
- $\begin{tabular}{ll} $\bigstar$ Quick press the vibration button on the remote to cycle through modes. \end{tabular}$
- Quick press the +/- button on the remote to cycle through speeds.





#### CHARGE

- $\star$  The light will blink while the device is charging.
- **★** The light will become solid once the device is fully charged.

